PERMAS

and improve endurance

Freeform Optimization

 Design space: Definition by node set on the design surface, complete optimization model by VisPER.

 Constraints: Equivalent stress, principal stress, stress differences, effective plastic strain, weight, compliance, displacement, element quality, release direction, node values from external tools (e.g. safety factors).

 Objectives: Stress (inside and outside of design space), effective plastic strain, weight, compliance, node values from external tools (e.g. safety factors).

 Analysis methods: Linear and nonlinear static analysis (incl. contact), linear and nonlinear, steady-state and transient heat transfer analysis, frequency response analysis.


 Optimization methods: Homogenization of stresslike quantities with Optimality Criteria (OC). For other quantities used as constraints, a combined method of OC and mathematical optimization is applied.


 Relaxation: Of meshes at surfaces and in the design space for larger thickness changes and better element quality.

 Results: History plots, new node coordinates, thickness change, coordinate change, stress change, export of surface geometry.



Save weight





Definition of surface node set and generated design space

Normal change

(Sum of geometry

changes normal

over all iterations)

to the surface

1.15

0.96

0.76

0.57

0.38


-0.00

-0.16

-0.38

-0.58

-0.77



Typical optimization definition process:

 Selection of surface node set for definition of design space

- Weight objective (for design space)
- Stress limit like von Mises or principal stresses (for design space)
- Additionally: displacement conditions to limit local displacements (outside of design space)

Coordinate change

(Length of vector

final coordinates)

between initial and


Easy set-up of optimization model


Nodal Point Stress Mises Iteration 10 v.Mises Vis**PER**

VisPER features the graphically guided description and post-processing of optimization models by:

- Defining the design space,
- Defining the design parameters,
- Selecting objective function and design constraints,
- Defining manufacturing constraints,
- Post-processing of all optimization results.

Nodal stress change by optimization





• Growing or shrinking of the wall thickness (with mesh relaxation)

Coordinate Change Col 1

1.15

0.96

0.76

0.57

0.16

-0.00


-0.16


-0.38

-0.58

-0.77 -0.96

- Always in normal direction (updated in each iteration)
- Useful for complex freeform surfaces (like for cast parts)





For more information about PERMAS contact:

In France: INTES France 40 rue Sadi Carnot 78120 Rambouillet, France Phone +33-1-3483 1989 Fax +33-1-3483 2028 E-mail: permas@intes.fr http://www.intes.fr

<u>In Japan:</u> INTES Japan 4th floor, Owlcourt, 1-3-6, Nishiikebukuro, Toshima-ku, Tokyo, 171-0021, Japan Phone +81-3-6915-2848 Fax +81-3-6915-2849 E-mail: info@intes.jp http://www.intes.jp

> International: INTES GmbH Schulze-Delitzsch-Str. 16 70565 Stuttgart, Germany Phone +49-711-78499-10 Fax +49-711-78499-10 E-mail: info@intes.de http://www.intes.de